

## **Take Digital Pictures of the TD4100 OIW Monitor**

Take digital pictures of the monitor's installation that you could forward to us for inspection. The pictures need to be at least 2 Megapixels in resolution and the picture clarity needs to be sharp and clear for inspection. The following details in various pictures would help us evaluate the installation:

- 1) An overall view of the monitor.
- 2) A detailed view of the sample inlet and drain connection at the monitor.
- 3) A detailed view of the sample inlet connection where the sample is being withdrawn.
- 4) A detailed view of the monitor's electrical connection at the monitor.
- 5) A detailed view of the compressed air connection at the monitor.
- 6) A detailed view of the compressed air connection at the source / air drier.

*Note: Item 2 above is extremely important. A pressurized drain system can instantaneously damage the monitor and create a safety hazard in certain circumstances.*



